TABLE 1. ‘Command Manager’ Operations

Function	Inputs	Outputs
Initialize (This operation must be invoked before starting the RTX scheduler)	Address of “Command Device” to use for input. Address of “Command Log” to use for command logging and echoing. Address of a fixed length collection of “Command Handlers”	none
Command Manager’s Main Task Function (invoked by RTX scheduler)	none	never returns