TABLE 1. 'Watchdog Device' Operations

Function	Inputs	Outputs
Initialize	none	none
Set Time-out Period	The time it takes for the timer to go off (in TBD Units)	none
Touch	none	none
Force Hardware Reset	none	Forces the Watchdog Timer to expire, causing a hardware reset of the Back End Processor